

**Preview of Prep Check 4.**

---

1. True or False: The gravity flux of solids in Type III sedimentation increases monotonically with increasing solids concentration
2. Which of the following shapes are used most commonly for Type III sedimentation in a continuous flow clarifier?
3. .Type III sedimentation results from which **one** of the following phenomena?
4. Weirs usually have V-notches for which **two** of the following reasons: